



227 Lincoln Street Seawall East 50'. Place additional rock where erosion has occurred. Access is from above. No rocks will be place seaward of existing wall nor will rocks be placed higher as per the State of Washington