City of Port Townsend

Lawrence Street Multimodal Improvements

Walker Street Collision Data Summary

	Walker	Lawrence	·
Report mm-yyyy	Direction	Direction	Cause
EE76620 05-2024	SB	WB	Pulled out from a stopped position
EB73631 08-2021	N/A (Harrison)		
EE21153 11-2023	SB	EB	Pulled out from a stopped position
EC33071 03-2022	SB	EB	Pulled out from a stopped position
EA50158 07-2020	N/A	EB	Rear-ended a car turning left
	(Lawrence)		
EA55323 08-2020	N/A (Cass)	WB	
ED73017 05-2023	SB	WB	Pulled out (thought it was a 4-way
			stop)
EE12712 10-2023	SB	WB	Pulled out from a stopped position
			(by interpretation)
E740096 11-2017	SB	WB	Failed to stop (distracted)
E692052 07-2017	SB	EB	Failed to stop (yield)
E683993 06-2017	NB	WB	Failed to stop (or rolled through the
			stop)
E585230 09-2018	SB	EB	Pulled out from a stopped position
E733241 11-2017	SB	EB	Pulled out from a stopped position
E581740 09-2016	N/A (Harrison)	EB	Turned left in front of EB vehicle
E499946 12-2015	SB	EB	Failed to stop

Yellow = "Pulled out from stopped position"

Blue = "Failed to stop"

Green = duplicate collision from Nov 21 memo